Apex Precison Analytical Services, Inc.



An Independent Laboratory Providing Reliable Analysis with Professionalism and Honesty

ASBESTOS BULK REPORT

Date: April 5, 2013

ABC Company

Report: 0013-0000

Your Project Name for the Job

This document shall be considered a duly signed original report of the results obtained from the analyses performed. All analyses are done within government guidelines and regulations.

> Gary R. Simmons Laboratory Manager

Lab Comments on Project: N/A

Apex Precison Analytical Services, Inc.



An Independent Laboratory Providing Reliable Analysis with Professionalism and Honesty

PLM (Bulk) - Asbestos Analysis Report - Visual ID (EPA Method 600/R-93-116 Visual Area Estimation)

Turn-around time: 24 Hour

ABC Company Report Number: 0013-0000 123 Report Lane **Report Date:** April 5, 2013 Somewhere, TX 00000 Samples Collected: April 2, 2013 000-000-0000 **Date Received:** April 4, 2013

Contact: Your Name

ob ID / Site:	Your Project Name for the Job						
Client Sample Number	Lab Sample Number (by layer)	Color / Description / Fibrous / NonFibrous / Homogeneity	Asbestos Content Type & %	Non-Asbestos Fibrous Type & %	Matrix		
01	0013-0000-01	Brown / Insulation / Fibrous / Homogeneous	None Detected	Cellulose 15%	Binder		
02	0013-0000-02	Brown / Insulation / Fibrous / Homogeneous	None Detected	Cellulose 15%	Binder		
03	0013-0000-03A	White / Texture / Fibrous / Homogeneous	Chrysotile 3%	None Detected	Binder		
	0013-0000-03B	Brown,White / Sheetrock / Fibrous / Homogeneous	None Detected	Cellulose 10%	Binder		
04	0013-0000-04A	White / Texture / Fibrous / Homogeneous	Chrysotile 3%	None Detected	Binder		
	0013-0000-04B	Brown,White / Sheetrock / Fibrous / Homogeneous	None Detected	Cellulose 10%	Binder		
05	0013-0000-05A	White / Texture / Fibrous / Homogeneous	Chrysotile 3%	None Detected	Binder		
	0013-0000-05B	Brown,White / Sheetrock / Fibrous / Homogeneous	None Detected	Cellulose 10%	Binder		
06	0013-0000-06	White,Grey / 2x4 Ceiling Tile / Fibrous / Homogeneous	None Detected	Cellulose 45% Fibrous Glass 10%	Binder		
07	0013-0000-07	White,Grey / 2x4 Ceiling Tile / Fibrous / Homogeneous	None Detected	Cellulose 45% Fibrous Glass 10%	Binder		

Analytical results and reports are generated by Apex Precision Analytical Services at the request of and for the exclusive use of the person or entity (client) named on such report. Result, reports or copies of same will not be released by Apex Precision Analytical Services to any third party without the written request from client. These results only repesent the materials submitted. Supporting laboratory documentation is available upon request. This report cannot be used to represent conditions at any other location, date or time and does not imply that this space is free from these or any other contaminants. No responsibility or liability is assumed for the manner in which these results are used or interpreted. This must not be used to claim product endorsement by NVLAP or any government agency of the United States. Apex Precision Analytical Services reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

NVLAP Lab Code: 200633-0 PLM TDSHS Asbestos License#: 30-0312 PLM/PCM

Apex Precison Analytical Services, Inc.



An Independent Laboratory Providing Reliable Analysis with Professionalism and Honesty

PLM (Bulk) - Asbestos Analysis Report - Visual ID (EPA Method 600/R-93-116 Visual Area Estimation)

ABC Company Report Number: 0013-0000 123 Report Lane **Report Date:** April 5, 2013 Somewhere, TX 00000 Samples Collected: April 2, 2013 000-000-0000 **Date Received:** April 4, 2013 **Contact: Your Name** Turn-around time: 24 Hour

ob ID / Site:	Your Project Name for the Job					
Client Sample Number	Lab Sample Number (by layer)	Color / Description / Fibrous / NonFibrous / Homogeneity	Asbestos Content Type & %	Non-Asbestos Fibrous Type & %	Matrix	
08	0013-0000-08	White,Grey / 2x4 Ceiling Tile / Fibrous / Homogeneous	None Detected	Cellulose 45% Fibrous Glass 10%	Binder	
09	0013-0000-09A	Blue / 12x12 Floor Tile / Fibrous / Homogeneous	None Detected	Cellulose <1%	Binder	
	0013-0000-09B	Black / Mastic / Fibrous / Homogeneous	Chrysotile 5%	None Detected	Binder	
10	0013-0000-10	Positive Stop				
11	0013-0000-11	Positive Stop				

Analytical results and reports are generated by Apex Precision Analytical Services at the request of and for the exclusive use of the person or entity (client) named on such report. Result, reports or copies of same will not be released by Apex Precision Analytical Services to any third party without the written request from client. These results only repesent the materials submitted. Supporting laboratory documentation is available upon request. This report cannot be used to represent conditions at any other location, date or time and does not imply that this space is free from these or any other contaminants. No responsibility or liability is assumed for the manner in which these results are used or interpreted. This must not be used to claim product endorsement by NVLAP or any government agency of the United States. Apex Precision Analytical Services reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

NVLAP Lab Code: 200633-0 PLM TDSHS Asbestos License#: 30-0312 PLM/PCM