

Chain of Custody

APASI#:

for office use only

3420-2320

Date Collected: 05/05/2020	Date Sent: 05/05/2020
Contact: Paul Dehlinger	Special Instructions:
Company: Austin Environmental	
Address: P.O. Box 143263	P.O. #:
Austin Texas 78714	E-Mail: pdehlinger@austinenv.com
Phone: 512) 587-8036	Fax:

Turn Around Time: (Circle One) Urgent/ASAP 24 Hours 48Hours 72 Hours 5 Days

Client Job Number/Name: LEE DRAIN BUILDING
NEA20-86 1900 W. AVE I HUNTSVILLE TX

Mycology(Mold) Spore Trap-Air Samples

☐ Fungal/Mold spore count by Air-O-Cell, Cyclex (d), BioCell, or other spore trap cassette/device

Mycology(Mold) Bulk ID Samples

☐ Fungal/Mold Identification – bulk sample, tape lift, swab

Phase Contrast Microscopy(PCM)-Air Samples

☐ Fiber Concentration by NIOSH Method 7400 Issue 2

Polarized Light Microscopy(PLM)-Bulk Samples

☒ Asbestos Identification (Visual Estimation)

by EPA 600/R-93/116 Method

☐ Asbestos Identification (Point Count)

by EPA 600/M4-82-020 Method

☐ Asbestos Identification (Soil/Prep)

by Gravimetric Reduction

Industrial Hygiene-Air & Bulk Samples

☐ (RCF) Refractory Ceramic Fiber (Bulk) Identification

(Visual Estimation) by Polarized Light Microscopy

☐ Total Nuisance Dust (Air) by NIOSH Method 0500

☐ Total Respirable Dust (Air) by NIOSH Method 0600

Sample #:	Location/Description:	Volume
1A	COVERBASE/MASTIC RM204	
1B	↓	
1C	↓ RM205	
2A	FLOOR TILE/MASTIC RM205	
2B	↓	
2C	↓ RM204	
3A	CEILING TILE RM204	
3B	↓ RM205	
3C	↓ RM1	
4A	DRYWALL TEXTURE RM204	
4B	↓	
4C	↓ RM205	

Relinquished by: DMU

Received by: Laura Brown

Date: 05/05/2020

Time:

Date: 5/6/20

Time: 0900